Measurement Range: DC  $\pm$  1000A

Accuracy: 0.02%


# **IIT1000 Industrial Control Level Current Transducer**

IIT1000 has a high gain and measurement accuracy in the full bandwidth range, due to the application of the multi-point zero-flux technology system and high-frequency ripple sensing channel on top of currently existing DC sensor technology.

The multi-point zero-flux technology system secures the high accuracy by utilizing the technology combination of exciting magnetic flux closed-loop control, self-excited magnetic flux gate and multi-closed-loop control that realizes the closed-loop control between excitation magnetic flux and AC/DC magnetic flux generated by primary current, while the high-frequency ripple sensing channel allows the sensor to have the high performance over the full bandwidth range.

## Product photo





Email: info@hangzhiprecision.com Tel: +86 (0)755 8259 3440

Website: www.hangzhiprecision.com

Measurement Range: DC $\pm$ 1000A

Accuracy: 0.02%

### **Key Technologies**

- ♦ Excitation closed-loop control technology
- ♦ Self-excitation demagnetization technology
- ♦ Multi-point zero-flux technology
- ♦ Temperature control compensation technology
- Multi-range automatic switching technology

### **Features**

- ♦ Insulated measurement between primary and secondary side
- ♦ Excellent linearity and accuracy
- ♦ Extremely low temperature drift
- ♦ Extremely low zero drift

♦ Ship: Electric driven ship

♦ Car: Electric car

♦ Broad band and low response time

♦ Rail Transit: EMU, Metro, Trolly car

♦ Strong anti-electromagnetic interference

# **Application Domain**

- ♦ Medical Equipment: Scanner, MRI
- ♦ Power Industry: Converter, Inverter
- ♦ Renewable Energy: Photovoltaic, Wind energy
- ♦ Testing Instrument: Power analyzer, High-precision power supply
- ♦ Smart Power Grid: Power generation and battery monitoring, Medium low voltage substation
- ♦ Industry Control: Industrial motor drive, UPS, Welding, Robot, Hoist, Elevator, Ski lift

### **Electrical Performance**

Symbol	Measuring Conditions	Min	Тур	Max	Unit
I <sub>PN_DC</sub>	_	_	±1000	_	Adc
I <sub>PN_AC</sub>	_	_	707	_	Aac
I <sub>РМ</sub>	_	-	_	±1200	Adc
Uc	_	±14.2	±15	±15.8	V
Ic	Rated primary current	±30	±700	±830	mA
$K_N$	Primary/secondary	1500:1	1500:1	1500:1	_
Isn	Rated primary current	-	±0.667	_	Α
R <sub>M</sub>	_	0	1.5	3	Ω
	IPN_DC IPN_AC IPM Uc Ic KN ISN	I <sub>PN_DC</sub> — I <sub>PN_AC</sub> — I <sub>PM</sub> — U <sub>C</sub> — I <sub>C</sub> Rated primary current K <sub>N</sub> Primary/secondary I <sub>SN</sub> Rated primary current	I <sub>PN_DC</sub> —         —           I <sub>PN_AC</sub> —         —           I <sub>PM</sub> —         —           Uc         —         ±14.2           I <sub>C</sub> Rated primary current         ±30           K <sub>N</sub> Primary/secondary         1500:1           I <sub>SN</sub> Rated primary current         —	I <sub>PN_DC</sub> —         ±1000           I <sub>PN_AC</sub> —         707           I <sub>PM</sub> —         —           Uc         —         ±14.2         ±15           I <sub>C</sub> Rated primary current         ±30         ±700           K <sub>N</sub> Primary/secondary         1500:1         1500:1           I <sub>SN</sub> Rated primary current         —         ±0.667	I <sub>PN_DC</sub> —         ±1000         —           I <sub>PN_AC</sub> —         —         707         —           I <sub>PM</sub> —         —         ±1200           Uc         —         ±14.2         ±15         ±15.8           I <sub>C</sub> Rated primary current         ±30         ±700         ±830           K <sub>N</sub> Primary/secondary         1500:1         1500:1         1500:1           I <sub>SN</sub> Rated primary current         —         ±0.667         —

<sup>\*</sup> refers to AC effective value

Email: info@hangzhiprecision.com Tel: +86 (0)755 8259 3440

Website: www.hangzhiprecision.com

Measurement Range: DC  $\pm$  1000A

Accuracy: 0.02%

# **Accuracy Measurement**

Parameter	Symbol	Measuring Conditions	Min	Тур	Max	Unit
Accuracy	$X_{G}$	Input direct current, full temperature range	_	_	0.02	%
Linearity error	ε <sub>L</sub>	Full temperature range	_		15	ppm
Zero offset current	Іот	@25℃	_	_	±5	μA
Zero offset current	lo	Full temperature range	_	_	±10	μΑ
Step response time to 90%IPN_DC	t <sub>r</sub>	di/dt of 100A/μs	_	_	1	μs
di/dt accurately followed	di/dt	_	200	_	_	A/µs
Frequency bandwidth (-3dB)	BW	_	0	_	100	kHz

# **Safety Characteristics**

Parameter	Symbol	Measuring Conditions	Value	Unit
Insulation voltage / Between primary and secondary	Ud	50Hz,1min	5	KV
Impulse withstand voltage / Between primary and secondary	Uw	50µs	10	KV
Creepage distance / Between primary and shield	<b>d</b> CP	_	11	mm
Clearance distance / Between primary and shield	d <sub>Cl</sub>	_	11	mm
Comparative tracking index	CTI	IEC-60112	275	V

# **General Characteristics**

Parameter	Symbol	Measuring Condition	Min	Тур	Max	Unit
Ambient operating	T <sub>A</sub>	_	-40	_	+85	°C
temperature						
Ambient storage temperature	Ts	_	-40	_	+85	°C
Relative humidity	RH	_	20		80	%
Mass	М	<del>_</del>		900±10		g

**Tel:** +86 (0)755 8259 3440 Website: www.hangzhiprecision.com

Measurement Range: DC  $\pm$  1000A

Accuracy: 0.02%

## Safety



### **Cautions**

This specifications documents provide users with relevant precautions for installation, commissioning, operation and maintenance. Please read carefully before installation and use. This manual is provided with the product, please keep it in a proper place for reference during maintenance.

The device must be used according to the manufacturer specifications, otherwise there are risks to damage the device, other equipment connected, and safety risks to operators.

Always inspect the device and its accessories, and confirm they are in good status before energize the device.

If you find any damage to the device housing, fixing, power cord, connecting cables, or connected equipment, immediately disconnect the device from the power source.

If you have concerns about the safe operation of the equipment, you should immediately shut down the equipment and the corresponding accessories, and get in touch with the technical support department of our company as soon as possible to communicate and solve the problem.



# **Danger**

The current sensor is not allowed to be used when the secondary output is open-circuited, that is, when the primary has current or the sensor is powered on, the secondary output terminal is not allowed to be disconnected; only when the bus has no current and the sensor is not powered on, the current output terminal of the sensor can be disconnected. Otherwise, high voltage may be induced and there is a danger of electric shock or equipment damage.

When you need to move the product, please be sure to cut off the power first and unplug all the connecting cables connected to it.

Email: info@hangzhiprecision.com

**Tel:** +86 (0)755 8259 3440 **Website:** www.hangzhiprecision.com

Measurement Range: DC $\pm$ 1000A

Accuracy: 0.02%

### **Operating Status Instructions**

#### ♦ Normal status:

The green light indicator is on when the device is running normally:

After the device is powered on, the green indicator is on when the device is running normally. When the green light is off, you should check whether the power supply of the transducer is normal as the first step.

#### ♦ Fault status:

The green light is blinking when the current overloads.

Trouble-shooting:


If the power supply is normal, the green light indicator keeps on blinking, then the primary current is over the specified measurement range and the transducer will be in overload mode. In this mode, the transducer will be working in non-zeroflux mode, the secondary and primary currents are not in proportion. When the current recovers to the specified measurement current range, the current transducer returns to normal, green light indicator will be on.

## Connection system

#### 1. Phoenix terminal pin function definition

Pin	1	2	3	4
Definition	+15V Supply	-15V Supply	I_Output	GND

**IIT Series Transducer** 



#### Test instruction:

The primary current  $I_P$  can be obtained by measuring the test current  $I_s$  flowing through  $R_M$  or the voltage  $U_R$  across  $R_M$ :

$$I_{P} = K_{N} * I_{S} = K_{N} * (U_{R}/R_{M})$$

Add: Rm 330, Building B, Huayuan Hi-Tech Innovation Park, Baoyuan Rd, Bao'an District, Shenzhen, China P.R. Email: info@hangzhiprecision.com

**Tel:** +86 (0)755 8259 3440


Website: www.hangzhiprecision.com


Measurement Range: DC  $\pm$  1000A

Accuracy: 0.02%

## **Dimensions**

Unit: mm





# Packing List & Dimensions

Package dimensions (L x W x H): 157mm x 155mm x 110mm

Item	Description	Quantity	Comments
IIT1000	Current Transducer	1	1

Tel: +86 (0)755 8259 3440 Website: www.hangzhiprecision.com